




R.P.M. 1450 - 950



Curve N°	Code	Type	MOTOR			Power Supply	DN mm	Free Pass. mm	Weight Kg	code	⊕
			Nominal P P2 (kW)	Nominal I I (A)	Starting I Is (A)						
1	7001128	X411R2C2-P60LA5	7,1	13,5	64,8	3ph 400/690V-50Hz	DN 100	60	167	7007459	
2	7006395	X411R2C1-P60LA5	7,1	13,5	64,8	3ph 400/690V-50Hz	DN 100	60	167	7007449	
3	7000157	X413R2C2-P80LA5	10,1	22	121	3ph 400/690V-50Hz	DN 100	80	220	7007448	
4	7002876	X413R2C1-P80LA5	12,1	27	148,5	3ph 400/690V-50Hz	DN 100	80	220	7007435	
5	7008913	X618R2C2-S100LA5	11	23	124,2	3ph 400/690V-50Hz	DN 150	100	368	-	
6	7002474	X618R2C1-S100LA5	13,6	27,5	148,5	3ph 400/690V-50Hz	DN 150	100	368	-	
7	7001101	X418R2C3-S100LA5	25	48	283,2	3ph 400/690V-50Hz	DN 150	100	595	-	
8	7005834	X418R2C2-S100LA5	35,7	65,5	386,4	3ph 400/690V-50Hz	DN 150	100	595	-	

FOR FURTHER INFORMATION PLEASE CONTACT US:

TELEPHONE: (011) 792 9550/1/2, FAX: (011) 792 9553

e-mail: eeeaman@mweb.co.za Website: ernestee.co.za